		AND HUMAN SERVICES & MEDICAID SERVICES	454	4/04/10	FORM	: 02/18/201 APPROVEI : 0938-039
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTI A. BUILDIN	PLE CONSTRUCTION  G 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED		
445162		B. WING _		02/17/2010		
NAME OF PROVIDER OR SUPPLIER  ASBURY PLACE AT JOHNSON CITY			1 J	REET ADDRESS, CITY, STATE, ZIP CODE 05 WEST MYTRLE AVENUE OHNSON CITY, TN 37604		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		PREFIX TAG			(X5) COMPLETION DATE
K 038 SS=E	Exit access is arran	FETY CODE STANDARD ged so that exits are readily es in accordance with section	K 038	K 038 - Snow has been cleare sidewalks.  All means of egress will be free of impediments and readily accessible times.  All facilities (maintenance) staff wireeducated on NFPA 101 life safet standards 7.1 and 19.2.1.		
	This STANDARD is not met as evidenced by: Based on observation, the facility failed to assure exit access is arranged that exits are readily accessible at all times in accordance with 7.1.  The findings include:  Observation on February 17, 2010 at 10:00 a.m. revealed 2 of 3 sidewalks were not cleared of snow.  NFPA 101 LIFE SAFETY CODE STANDARD  Fire drills are held at unexpected times under varying conditions, at least quarterly on each shift. The staff is familiar with procedures and is aware that drills are part of established routine.  Responsibility for planning and conducting drills is assigned only to competent persons who are qualified to exercise leadership. Where drills are conducted between 9 PM and 6 AM a coded announcement may be used instead of audible alarms. 19.7.1.2  This STANDARD is not met as evidenced by: Based on observation, the facility failed to assure fire drills were conducted quarterly on each shift.  The findings include:		K 050	Facilities director will do audits to ascertain the means of egress is accessible and functionality of locking mechanisms upon actuation of the fire alarm system.  Audits will be performed biweekly for four (4) weeks, monthly for two (2) months and then a quarterly audit.  The results of the audits will be reviewed at the Quality Assurance Committee meeting monthly for three (3) months and recommendations made as appropriate  K 050 - Fire drill has been performed on		3/31/10
				first shift.  Fire drills will be performed in accordance with life safety code standard 19.7.1.2.		
				Fire drills will be performed at unexpected times under varying conditions at least quarterly on eashift. Staff is familiar with procedules aware that drills are a part of all established routine.	ires and	3/31/1
BORATORY	DIRECTOR'S OR PROVIDE	R/SUPPLIER REPRESENTATIVE'S SIGN	ATURE	TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 02/18/2010 FORM APPROVED OMB NO. 0938-0391

NAME OF PROVIDER OR SUPPLIER  ASBURY PLACE AT JOHNSON CITY    (24) ID   SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY OR LSC IDENTIFYING INFORMATION)   TAG   PREPRIX TAG   PREPRIATED FOR STATE (FIRST COMPONENT)   TAG   PREPRIX TAG   PREPRIATED FOR STATE (FIRST COMPONENT)   TAG   PREPRIX TAG   PREPRIATED FOR STATE (FIRST COMPONENT)   TAG   PREPRIX TAG   PREPRI	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  445162		IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING		COMPL	(X3) DATE SURVEY COMPLETED	
ASBURY PLACE AT JOHNSON CITY    105 WEST MYTRLE AVENUE JOHNSON CITY, TN 37604			445162				02/	02/17/2010
Regulatory or list identifying information)  Regulatory or list identifying information)  Record review on February 17, 2010 at 9:00 a.m. revealed first shift falled to perform a fire drill the 4th quarter of 2009.  NFPA 101 LIFE SAFETY CODE STANDARD  Means of egress are continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. No furnishings, decorations, or other objects obstruct exits, access to, egress from, or visibility of exits.  This STANDARD is not met as evidenced by: Based on observation, the facility failed to assure the corridors in the means of egress were maintained clear of all obstructions.  The findings include:  Observation on February 17, 2010 at 9:45 a.m. revealed one (1) ice cart, wheelchairs, isolation carts and blood pressure stands stored within the corridor.  K 050  Staff has been re-educated on the fire plan.  The administrator or Designee will audit fire drill logs quarterly to ascertain their completeness in accordance with life safety code standard 19.7.1.2  The results of the audits will be reviewed at the Quality Assurance Committee meeting monthly for three (3) months and recommendations made as appropriate  K 072 - Ice carts, wheel chairs, and isolation carts stored within corridor have been removed.  All corridors and means of egress have been cleared of all obstructions  All means of egress must be continuously maintained free of all obstructions or impediments to fully use in the case of fire or an emergency. No furnishings, decorations, or other objects obstruct exits, access to, egress from, or visibility of exits. Life safety code standard 7.1.10			N CITY		105	WEST MYTRLE AVENUE		
Record review on February 17, 2010 at 9:00 a.m. revealed first shift failed to perform a fire drill the 4th quarter of 2009.  K 072 SS=F  Means of egress are continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. No furnishings, decorations, or other objects obstruct exits, access to, egress from, or visibility of exits.  7.1.10  This STANDARD is not met as evidenced by: Based on observation, the facility failed to assure the corridors in the means of egress were maintained clear of all obstructions.  The findings include:  Observation on February 17, 2010 at 9:45 a.m. revealed one (1) ice cart, wheelchairs, isolation carts and blood pressure stands stored within the corridor.	PREFIX	(EACH DEFICIENC)	Y MUST BE PRECEDED BY FULL	PREFIX	۲	(EACH CORRECTIVE ACTION SI CROSS-REFERENCED TO THE AF	HOULD BE	COMPLETION DATE
furnishings, decorations, or other objects obstruct exits, access to, egress from, or visibility of exits.  7.1.10  This STANDARD is not met as evidenced by: Based on observation, the facility failed to assure the corridors in the means of egress were maintained clear of all obstructions.  The findings include:  Observation on February 17, 2010 at 9:45 a.m. revealed one (1) ice cart, wheelchairs, isolation carts and blood pressure stands stored within the corridor.  The results of the audits will be reviewed at the Quality Assurance Committee meeting monthly for three (3) months and recommendations made as appropriate  K 072 - Ice carts, wheel chairs, and isolation carts stored within corridor have been removed.  All corridors and means of egress have been cleared of all obstructions  All means of egress must be continuously maintained free of all obstructions or impediments to fully use in the case of fire or an emergency. No furnishings, decorations, or other objects obstruct exits, access to, egress from, or visibility of exits. Life safety code standard 7.1.10	K 072 SS=F	Record review on Frevealed first shift of 4th quarter of 2009 NFPA 101 LIFE SA Means of egress a of all obstructions of the structions of the structions of the struction of the	February 17, 2010 at 9:00 a.m. railed to perform a fire drill the continuously maintained free or impediments to full instant		72	olan. The administrator or Designee fire drill logs quarterly to ascer completeness in accordance v	will audit tain their vith life	
This STANDARD is not met as evidenced by: Based on observation, the facility failed to assure the corridors in the means of egress were maintained clear of all obstructions.  The findings include:  Observation on February 17, 2010 at 9:45 a.m. revealed one (1) ice cart, wheelchairs, isolation carts and blood pressure stands stored within the corridor.  Isolation carts stored within corridor have been removed.  All corridors and means of egress have been cleared of all obstructions All means of egress must be continuously maintained free of all obstructions or impediments to fully use in the case of fire or an emergency. No furnishings, decorations, or other objects obstruct exits, access to, egress from, or visibility of exits. Life safety code standard 7.1.10		furnishings, decorations, or other objects obstruct exits, access to, egress from, or visibility of exits.				the Quality Assurance Committed monthly for three (3) months and	e meeting	Ī
maintaining and egress free of obstructions and storage of items in corridors.  Administrator or Designee will visually audit corridors to ascertain means of egress is clear from obstructions weekly		Based on observat the corridors in the maintained clear of The findings includ Observation on Fei revealed one (1) iccorts and blood pre	ion, the facility failed to assure means of egress were all obstructions. e: bruary 17, 2010 at 9:45 a.m. e cart, wheelchairs, isolation			K 072 - Ice carts, wheel chairs, and isolation carts stored within corridor have been removed.  All corridors and means of egress have been cleared of all obstructions.  All means of egress must be continuously maintained free of all obstructions or impediments to fully use in the case of fire or an emergency. No furnishings, decorations, or other objects obstruct exits, access to, egress from, or visibility of exits. Life safety code standard 7.1.10  Staff have been re-educated on maintaining and egress free of obstructions and storage of items in corridors.  Administrator or Designee will visually audit corridors to ascertain means of		3/31/

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: XWIX21

Fac Monthly times three (3).

sheet Page 2 of 2

The results of the audits will be reviewed at the Quality Assurance Committee meeting monthly for three (3) months and recommendations made as appropriate